EAST Search History

Ref#	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L7	33	(US-20070165213-\$ or US-20050018199-\$).did. or (US-4401893-\$ or US-4645337-\$ or US-3652863-\$ or US-3737665-\$ or US-3989387-\$ or US-5493123-\$ or US-6236734-\$ or US-6404489-\$ or US-6509967-\$ or US-7142295-\$ or US-5894345-\$ or US-5790247-\$ or US-5627638-\$ or US-5355213-\$ or US-4808813-\$ or US-6226080-\$ or US-5637864-\$ or US-5117120-\$ or US-4652745-\$ or US-468120-\$ or US-3947131-\$ or US-5137355-\$ or US-5699153-\$ or US-6388745-\$ or US-6605807-\$ or US-5268735-\$).did. or (US-7292332-\$ or US-0552641-\$ or US-3985454-\$ or US-4668861-\$ or US-7369240-\$).did.	US-PGPUB; USPAT	OR	ON	2008/06/12
L8	13	7 and ((liquid fluid oil) with (panel plate glass))	US-PGPUB; USPAT; USOCR	OR	ON	2008/06/12 07:00
L9	7	("4492477" "4725139" "4808813" "5790247" "6151125" "6346713" "6437357").PN. OR ("7292332").URPN.	US-PGPUB; USPAT; USOCR	OR	ON	2008/06/12 07:04
L10	1	("2005/0018199").URPN.	USPAT	OR	ON	2008/06/12 08:54
L12	449440	((clear glass translucent transparent) with (film panel sheet web))	US-PGPUB; USPAT; USOCR	OR	ON	2008/06/12 08:57
L13	3481	((analyz\$4 characteriz\$6 detect\$4 determin\$6 evaluat\$4 inspect\$4 measur\$4) with (anomal\$4 condition flaw defect error mistake problem inclusion fault bubble) with (clear glass translucent transparent) with (film panel sheet web))	US-PGPUB; USPAT; USOCR; EPO; JPO; IBM_TDB	OR	ON	2008/06/12 08:58

L15	970	((analyz\$4 characteriz\$6 detect\$4 determin\$6 evaluat\$4 inspect\$4 measur\$4) with (anomal\$4 condition flaw defect error mistake problem inclusion fault bubble) with (clear glass translucent transparent) with (film panel sheet web)).ab.	US-PGPUB; USPAT; USOCR; EPO; JPO; IBM_TDB	OR	ON	2008/06/12 09:08
L16	481160	((liquid fluid oil) with (panel plate glass))	US-PGPUB; USPAT; USOCR	OR	ON	2008/06/12 09:08
L17	37	15 and 16	US-PGPUB; USPAT; USOCR	OR	ON	2008/06/12 09:09
L18	15573	(total with internal with reflection)	US-PGPUB; USPAT	OR	ON	2008/06/12 09:11
L19	33	13 and 18	US-PGPUB; USPAT; USOCR	OR	ON	2008/06/12 09:11
L20	140303	(interface contact input) with (flexible malleable soft)	US-PGPUB; USPAT	OR	ON	2008/06/12 10:51
L21	88	13 and 20	US-PGPUB; USPAT	OR	ON	2008/06/12 10:51
L24	7	7 and ((plastic polymer acrylic) with (panel plate web sheet))	US-PGPUB; USPAT	OR	ON	2008/06/12 11:56
L25	32	7 and (human observ\$3 operat\$4)	US-PGPUB; USPAT	OR	ON	2008/06/12 12:01
S1	1	"584966" and fang.in.	US-PGPUB; USPAT; USOCR; EPO; JPO; IBM_TDB	OR	ON	2008/05/16 05:33
S4	4761	(356/237.1-241.6).ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; IBM_TDB	OR	ON	2008/05/16 05:58
S5	1356	(356/128-137).ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; IBM_TDB	OR	ON	2008/05/16 05:59
S6	2	(("4401893") or ("4645337")).PN.	US-PGPUB; USPAT; USOCR; EPO; JPO; IBM_TDB	OR	OFF	2008/05/16 06:00

S7	30356	((clear glass translucent transparent) with (film panel sheet web)).ab.	US-PGPUB; USPAT; USOCR	OR	ON	2008/05/16 06:31
S8	579039	((analyz\$4 characteriz\$6 detect\$4 determin\$6 evaluat\$4 inspect\$4 measur\$4) with (anomal\$4 condition flaw defect error mistake problem inclusion fault bubble)).ab.	US-PGPUB; USPAT; USOCR; EPO; JPO; IBM_TDB	OR	ON	2008/05/16 06:31
S9	184	S7 and S8	US-PGPUB; USPAT; USOCR	OR	ON	2008/05/16 06:31
S10	230493	refract\$4 with index	US-PGPUB; USPAT; USOCR; EPO; JPO; IBM_TDB	OR	ON	2008/05/16 06:31
S11	41	S9 and S10	US-PGPUB; USPAT; USOCR; EPO; JPO; IBM_TDB	OR	ON	2008/05/16 06:31
S12	11	("0552641" "4136961" "4808813" "5355213" "5627638" "5691811" "5790247" "5859364" "5894345").PN. OR ("6404489").URPN.	US-PGPUB; USPAT; USOCR	OR	ON	2008/05/16 08:32
S13	26	("3328000" "3394263" "3894806" "3947131" "4297032" "4468120" "4652745").PN. OR ("4808813").URPN.	US-PGPUB; USPAT; USOCR	OR	ON	2008/05/16 09:24
S14	24	("0552641" "1514386" "3328000" "3639067" "3985454" "4668861" "4678327" "4808813"). PN. OR ("5355213"). URPN.	US-PGPUB; USPAT; USOCR	OR	ON	2008/05/16 09:24
S15	21	("3892494" "3988068" "5355213").PN. OR ("5627638").URPN.	US-PGPUB; USPAT; USOCR	OR	ON	2008/05/16 09:24
S16	22	("4808813" "5177559" "5268735" "5355213" "5515159" "5631733"). PN. OR ("5790247"). URPN.	US-PGPUB; USPAT; USOCR	OR	ON	2008/05/16 09:28
S17	11	("4555179" "5137355" "5293538" "5699153"). PN. OR ("5894345"). URPN.	US-PGPUB; USPAT; USOCR	OR	ON	2008/05/16 09:28

S18	33	(US-20070165213-\$).did. or (US-4401893-\$ or US-4645337-\$ or US-3652863-\$ or US-4844613-\$ or US-3737665-\$ or US-3989387-\$ or US-5493123-\$ or US-6236734-\$ or US-6404489-\$ or US-6509967-\$ or US-7142295-\$ or US-7307714-\$ or US-5894345-\$ or US-5355213-\$ or US-4808813-\$ or US-6226080-\$ or US-5637864-\$ or US-3947131-\$ or US-5137355-\$ or US-5699153-\$ or US-6388745-\$).did. or (US-6605807-\$ or US-3985454-\$ or US-4668861-\$).did.	US-PGPUB; USPAT	OR	ON	2008/05/16
S19	15421	(total with internal with reflection)	US-PGPUB; USPAT	OR	ON	2008/05/16 10:04
S20	8	S18 and S19	US-PGPUB; USPAT	OR	ON	2008/05/16 10:04
S21	32	(US-20070165213-\$).did. or (US-4401893-\$ or US-4645337-\$ or US-3652863-\$ or US-3737665-\$ or US-3989387-\$ or US-65493123-\$ or US-6236734-\$ or US-6509967-\$ or US-7142295-\$ or US-7307714-\$ or US-5894345-\$ or US-5790247-\$ or US-5627638-\$ or US-5637864-\$ or US-5117120-\$ or US-5117120-\$ or US-5137355-\$ or US-6699153-\$ or US-6388745-\$ or US-6605807-\$).did. or (US-5268735-\$ or US-7292332-\$ or US-0552641-\$ or US-3985454-\$ or US-4668861-\$).did.	US-PGPUB; USPAT	OR	ON	2008/05/19
S22	446877	((clear glass translucent transparent) with (film panel sheet web))	US-PGPUB; USPAT; USOCR	OR	ON	2008/05/19 11:23

S23	1372843	(laser led (light adj emitting adj diode) ((light radiation illumination) adj source))	US-PGPUB; USPAT; USOCR	OR	ON	2008/05/19 11:24
S27	2233	((liquid oil water) with S22) with S23	US-PGPUB; USPAT; USOCR	OR	ON	2008/05/19 11:59
S28	30356	((clear glass translucent transparent) with (film panel sheet web)).ab.	US-PGPUB; USPAT; USOCR	OR	ON	2008/05/19 11:59
S29	434	S27 and S28	US-PGPUB; USPAT; USOCR	OR	ON	2008/05/19 12:00
S34	590207	((analyz\$4 characteriz\$6 detect\$4 determin\$6 evaluat\$4 find\$4 inspect\$4 measur\$4) with (anomal\$4 condition flaw defect error mistake problem inclusion fault bubble)).ab.	US-PGPUB; USPAT; USOCR; EPO; JPO; IBM_TDB	OR	ON	2008/05/19 12:35
S35	185	S28 and S34	US-PGPUB; USPAT; USOCR; EPO; JPO; IBM_TDB	OR	ON	2008/05/19 12:36
S36	32	S35 and (interface)	US-PGPUB; USPAT; USOCR	OR	ON	2008/05/19 12:36
S38	5083	S34 and (roll\$4 with (film panel sheet web))	US-PGPUB; USPAT; USOCR; EPO; JPO; IBM_TDB	OR	ON	2008/05/19 14:00
S39	602	\$22 and \$34 and (roll\$4 with (film panel sheet web))	US-PGPUB; USPAT; USOCR; EPO; JPO; IBM_TDB	OR	ON	2008/05/19 14:01
S40	43	S28 and S34 and (roll\$4 with (film panel sheet web))	US-PGPUB; USPAT; USOCR; EPO; JPO; IBM_TDB	OR	ON	2008/05/19 14:01

6/12/2008 12:14:59 PM

C:\ Documents and Settings\ JUnderwood\ My Documents\ EAST\ Workspaces\ Application 10584966.wsp